



## Aperio GT 450 DX Release 1.2.5 Patch Notice

Leica Biosystems is always looking for ways to further improve our customers' experience using our products. Our software patches often include new features, but also include improvements based on customer input and our own internal testing. Please make sure to read below for the details of this patch so you can get the best out of your product. Thank you for being a customer of Leica Biosystems.

### Improvements Included in the 1.2.5 Patch

Case #	Description
28974	Reduces risk of cyber vulnerabilities by closing ports not needed and removing unused libraries.
28976	Resolves an issue with PIN numbers being displayed in console logs.
28924	Fixes intermittent issue of Aztec barcodes not decoding.
28597	Fixes issue of barcodes (1D) not being read correctly
28949	Fixes issue involving barcodes decoding with unsupported characters.

Aperio GT 450 DX Release 1.2.5 Patch Notice  
Part Number/Revision: PN-0080, Revision A | Date: May 2025  
This document applies to Aperio GT 450 DX release 1.2.5 and later.



## Copyright Notice

- ▶ Copyright © 2025 Leica Biosystems Imaging, Inc. All Rights Reserved. LEICA and the Leica logo are registered trademarks of Leica Microsystems IR GmbH. Aperio, GT, and GT 450 are trademarks of Leica Biosystems Imaging in the USA and optionally in other countries. Other logos, product and/or company names might be trademarks of their respective owners.
- ▶ This product is protected by registered patents. For a list of patents, contact Leica Biosystems.

## User Resources

- ▶ For the latest information on Leica Biosystems Aperio products and services, please visit [www.LeicaBiosystems.com/Aperio](http://www.LeicaBiosystems.com/Aperio).

## Contact Information – Leica Biosystems Imaging, Inc.

Headquarters		Customer Support	
 <p>Leica Biosystems Imaging, Inc. 1360 Park Center Drive Vista, CA 92081 USA Tel: +1 (866)-478-4111 (toll free) Direct International Tel: +1 (760) 539-1100</p>		<p>Contact your local support representative with any query and service request.</p> <p><a href="http://www.leicabiosystems.com/contact-us/">www.leicabiosystems.com/contact-us/</a></p>	
European Union Authorized Representative		United Kingdom Responsible Person	
<div><div>EC</div><div>REP</div></div> <p>CEpartner4U Esdoornlaan 13 3951 DB Maarn The Netherlands</p>		<p>Leica Microsystems (UK) Limited Larch House, Woodlands Business Park Milton Keynes, England, United Kingdom, MK14 6FG</p>	
Switzerland Representative		Australia Sponsor	
<div><div>CH</div><div>REP</div></div> <p>Leica Microsystems (Schweiz) AG Max Schmidheiny-Strasse 201 9435 Heerbrugg, Switzerland</p>		<p>Leica Biosystems Melbourne Pty Ltd 495 Blackburn Rd, Mt Waverly Victoria 3149, Australia</p>	
Importers			
 <p>Leica Biosystems Deutschland GmbH Heidelberger Straße 17-19 69226 Nussloch, Germany</p>		<p>Leica Microsystems (UK) Limited Larch House, Woodlands Business Park Milton Keynes, England, United Kingdom, MK14 6FG</p>	

## Revision Record

Rev	Issued	Sections Affected	Detail
A	May 2025	All	New document.

